Site Name:		Operationa	al Period:		U.S. EPA Region 6			
Task Order 62 CES Environ	Date: 3-31-2015						ORDER	
Branch: Federal		Division/ Group: Response			mergency and Rapid Response Service			
WORK AUTHORIZED:								
Continue to pump water on sit								
Continue development of prof	iles and	disposal o	of sludge, li	quids, and solids.	المسم مدا)rumo		
Continue removal of water, oi	Manual College	, and was	te, from the	ASIS, Frac Tanks, Tot	EDDS P	oenonse	Manager	
Site Cerclis:# TXD 008950461		On-Scene Coordinator:						
Contract Number: EP - S6 - 07 -02		Gary Moore, USEPA			LeRoy Cassidey, CB&I Federal			
Task Order: 062		Date: 3.31.2015 Time:1700			Date: 3.31.2015 Time: 1700			
PERSONNEL ON-SITE:	QTY	Used	Unused	EQUIPMENT ON- SITE:		QTY	USED	Unused
Response Manager Foreman	1	1		Pick -up Tr	uck	2	2	
	1	1		Genera	ator	1	1	
	0	0		Trash Pun	nps	0	0	
Truck Driver/Equip Op	1	1		Utility Tra	ailer	0	0	
Laborer	2	2		Frac Tank w Li		1	1	
Health and Safety Manager	0	0		4,000 PSI Press Was		1	1	
PERSONNEL OFF-SITE				Open Top Roll	Off	8	8	
Subcontract Manager	1	1		Vacuum Truck Air Mo	over	1	1	
Transport and Disposal Coord	1	1		Carbon Vapor	Unit	1	1	
Field Cost Accountant	1	1	- 11 - 13	Skid S	teer	0	0	
				Vacuum/OT Bo	xes	22	22	
				9,000 lb Overhead	Lift	1	1	
				Storage Tra	ailer	1	1	
				Myers (Bean) Pu	ump	1	1	
				Air Compres	ssor	1	1	
				Acid Pu	ump	1	1	
WORK ACCOMPLISHED / A	MENDA	MENTS (p)	roblem areas	general comments, summary)(Input for	dav's 1. 90	00-5Pon5):	
The RM continued processing Met with Lonestar represental individual drums. Continue to	g of oper	rational-H	/Safety par 1004 with	perwork, procurements, TIBM. Worked with T&D	invoices,	and stat	us spread	sheets. f remainin
T&D Coordinator continued to streams. Worked with RM an with OSC and RM.								
Crew completed acid transfe	r from 40	46 T, PT	106 and R	O 1. Rinse acid poly tar	nks.			
osc	Date:		Time:	RMS, SON	se !	Dáte: 4.1.	2015	Time:0830
				7	(5		

Next OPERATIONAL PERIOD (administrative, tactical / resource status changes, special instructions, H&S)(Input for next DWO):

Rinse 4046. Stage items for final disposal or consolidation. Collect/dispose of ADS hose. Clean up area were previous transfers were staged.

Review AHA/(JSA) from SWSES for ST 1 with Health and Safety. Update spreadsheet on remaining waste.